

FIG. 1A

Digitized by srujanika@gmail.com




FIG. 1B




FIG. 2




FIG. 3A




FIG. 3B




FIG. 3C

7/13




FIG. 4




FIG. 5

9/13




FIG. 6




FIG. 7

AVERAGE SIGNAL LEVEL AFTER PASSING
THROUGH LOW BANDWIDTH RECEIVER




FIG. 8




FIG. 9




FIG. 10




FIG. 11